c. 1893

HA-1104 CAMERON-CURRIER LIVERY STABLES Havre de Grace, Md.

The Cameron-Currier Livery Stables is a two story building, rectangular in shape, and has a long, one and a shalf story wing attached to it built of vertical boards. The Livery Stables once provided horses and carriages to the town of Havre de Grace. When the automobile began to appear on the street in sufficient numbers to demand gasoline and mechanical servicing, the building became a service station.

MARYLAND HISTORICAL TRUST

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

<u> </u>							
1 NAME							
HISTORIC							
AND/OR COMMON Camer	on-Currier Livery S	Stables					
2 LOCATION	J						
	N. Stokes and Frank	clin Streets					
CITY, TOWN	Hours do Choos			congressional district			
	Havre de Grace vicinity OF Maryland		COUNTY Harford				
3 CLASSIFIC	ATION						
CATEGORY	CATEGORY OWNERSHIP STATUS			PRESENT USE			
DISTRICT X_BUILDING(S) STRUCTURE SITE OBJECT	PUBLIC X_PRIVATE BOTH PUBLIC ACQUISITION IN PROCESS BEING CONSIDERED	X.OCCUPIED _UNOCCUPIED _WORK IN PROGRESS ACCESSIBLE _YES: RESTRICTED _YES: UNRESTRICTED _NO	AGRICULTU _XCOMMERCIEDUCATIO*ENTERTAINGOVERNMEINDUSTRIAMILITARY	ALPARK NALPRIVATE RESIDENC MENTRELIGIOUS ENTSCIENTIFIC			
4 OWNER O	FPROPERTY		<u> </u>				
NAME	Oliver M. Currier	•	Telephone #:	0300600			
STREET & NUMBER	800 S. Market						
CITY, TOWN			2/078 STATE, Zip Code				
	e de Grace	VICINITY OF	Mary	land			
0011071101105	N OF LEGAL DESCR _{ETC.} Harford County C		Liber #: 4 Folio #: 8	05 0			
STREET & NUMBER	Main Street						
CITY, TOWN	Bel Air		STATE	Maryland			
6 REPRESEN	ITATION IN EXIST	NG SURVEYS					
DATE		FEDERAL	_STATE _COUNTY _	LOCAL			
DEPOSITORY FOR SURVEY RECORDS							
CITY, TOWN			STATE				

CONDITION

CHECK ONE

CHECK ONE

__EXCELLENT _XGOOD __DETERIORATED
__RUINS

_UNEXPOSED

__UNALTERED

_ORIGINAL SITE

__FAIR

X. ALTERED

__MOVED DATE____

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

The Cameron-Currier Livery Stables is located on the corner of N. Stokes Street and Franklin Street with houses on both sides of it. Entrance to the former livery stable, which became a gas and service station, is from Franklin Street. The building is painted white with a broad green stripe next to the roof, and at street level. Board and battens cover the building; the battens having molded profiles on the main block and plain profiles where repairs have been necessary. The building, two stories and rectangular in shape, has a long, one-and-a-half story wing attached to it, built of vertical boards. The wing, a slightly later addition, has a overhanging shed roof. Extending along the length of the rear wall of the wing is a one-story shed roof addition.

A modern porch with a flat roof supported by iron poles is attached to the east side, south elevation. The porch shelters the gas pumps, reminders of a time when the gas station was open for business.

First floor window openings on the main block, south elevation, have been altered to contain four-light sash suitable for a store front. On the second floor, gable end (east elevation) is a large window divided into 20 panes. Above it is a large rectangular opening through which hay was hauled. The opening contains a board and batten "door." A similar opening is found on the south elevation of the wing. On the south elevation, second floor, the east half of the wall contains small three-light openings, while slightly below them, on the west end, is a single square window having six lights. None of these windows open.

In the main block the first floor was used for carriages, the second floor for contained stalls for 12 horses, and the third floor loft provided storage for hay.

Sliding, double board and batten carriage doors are on the east and south elevations of the main block and on the south elevation of the wing.

A Dutch door with triangular butt hinges, on the west side, south elevation, main block gives entrance to the log ramp leading to the second floor horse stalls. Also on the south elevation is the modern service station entrance, containing a door with glass in the upper half.

The main block roof is steeply pitched with the ridge running east west; the rafter ends being exposed at the eaves. The wing roof is similar with a medium pitch and wide overhanging eaves.

1500-1599 1600-1699 1700-1799 X1800-1899 1900-	—AGRICULTURE X_ARCHITECTURE —ART —COMMERCE —COMMUNICATIONS	LECONOMICS LEDUCATION LENGINEERING LEXPLORATION/SETTLEMENT INDUSTRY LINVENTION	LITERATURE MILITARY MUSIC PHILOSOPHY POLITICS/GOVERNMENT	SCULPTURE SOCIAL/HUMANITARIAN THEATER TRANSPORTATION OTHER (SPECIFY) Local history
1900-	COMMUNICATIONS		POLITICS/GOVERNMENT	OTHER (SPECIFY)

STATEMENT OF SIGNIFICANCE

The Cameron-Currier Livery Stables once provided horses and carriages for the town of Havre de Grace. When the automobile began to appear on the street in sufficient numbers to demand gasoline and mechanical servicing the building became a service station.

This building is the third and last in which the livery stable was located; the first two buildings having been torn down. They were located on the corner of N. Union Street and Franklin Street and on Pearl Street. Cameron moved to the Franklin and Stokes Street location in 1892 and shortly after that in 1896, Oliver Currier, who was brought up in Mr. Cameron's home, bought the business from him.

This building provides a visual link with the history of transportation in Havre de Grace, as well as adding a note of architectural variety to its immediate neighborhood.

4 PO - AH

9 MAJOR BIBLIOGRAPHICAL REFERENCES

CITY OR TOWN

Harford County Directory, State Directories Publishing Company, 1953 Telephone conversation with Mr. Oliver M. Curry, October 12, 1976

CONTINUE	ON SEPARATE	SHEET I	F NECESSARY				
10 GEOGRA	PHICALDA	IA					
ACREAGE OF NO	MINATED PROPERTY _						
	NEADY DESCRIPTI	ON					
VERBAL BOU	INDARY DESCRIPTI	ON					
					D COLUMN P	NINDARIES	
LIST AL	LL STATES AND CO	UNTIES FOR	PROPERTIES OVERL	APPING STATE O	R COUNTY BO	JUNDARIES	

STATE			COUNTY				
			COUNTY	,			
STATE			COUNTY				
11 FORM P	REPARED B	Y					
NAME / TITLE			_	_			
	Marion Mor	ton - A	rchitectural	Surveyor			
ORGANIZATION					DATE	tember,	1976
5	Maryland H	istoric	al Trust			remoer,	<u> </u>
STREET & NUMB					TELEPHONE		
	21 State C	Circle					

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust
The Shaw House, 21 State Circle
Annapolis, Maryland 21401
(301) 267-1438

Annapolis, Maryland

DESCRIPTION (7) (Continued)

Both the main block and wing roofs are tin. The addition has an asphalt roof. Small brick chimneys are on the top of the south slope, gable end, main block and the north slope, gable end of the wing.





Cameron-Currier Livery Stables
HA-1104
N. Stokes and Franklin St, Havre de Grace
Marion Morton, July 1976
Southeast elevation